

**TO BE FILLED BY THE INSPECTING OFFICER
(ASSISTANT ENGINEER/ASSISTANT EXECUTIVE ENGINEER)**

No.AE/LSGD/AKD/FIT/10/2026-27

- 1 Name of school : ST MARYS CONVENT SCHOOL
2 Name of officer : Santo George
3 Location : ALAKODE
4 Period for which the certificate is issued : 2026-27
5 Type of building : RCC permanent
6 Nature of defect if any : NIL
a Foundation and basement : NIL
b Superstructure : NIL
c Doors and Windows : NIL
d wood work wrought and put up : NIL
e Roof : NIL
f Flooring : NIL
g Miscellaneous : NIL
7 Any major defects notice which will Render the building unsafe in any manner : NIL
8 Whether maintenance works have been done Properly : Yes
9 Whether the structure is sound or not for conducting classes : Yes, the structure is sound for conducting classes for normal weather condition .

L	B	H	Nos	Type
9.25M	6.60M	3.60M	4	CLASS ROOM
9.25M	3.00M	3.60M	1	STAIR ROOM
9.50M	6.00M	3.60M	12	GF
9.50M	6.00M	3.60M	13	FF
9.50M	6.00M	3.60M	13	SF
8.90M	7.50M	3.60M	10	GF
10.31M	2.48M	3.60M	1	GF
8.90M	7.50M	3.60M	12	FF
44.50M	17.64M	3.60M	1	SF
21.48M	10.33M	3.60M	1	STAGE

Notice:-

1. The stability of the structure should be examined also with reference to the altitude, intensity of wind exposure to flood etc.
2. Any additional observation is deemed necessary for the certificate may be furnished separately with the certificate.
3. Certified that the building was inspected by me on 26/05/2026 and found to be fit for the period for the reason stated above.
4. This certificate is applicable only to safety related to civil construction. Separate certificates for fire safety and safety of electrical installations, electrical lines/conduits shall be obtained from the concerned departments
5. Maintenance of the school premises should be done periodically. The inspecting officer is not liable for any unfortunate accidents in the school premises due to lack of security or periodic maintenance..
6. This certificate is only for the structural safety of the classrooms mentioned in this certificate. It does not cover safety in laboratories, kitchens, etc. 4. For any new construction in the school compound, should be intimated and a permit should be obtained from LSGI. Safety measures such as barricades must be ensured.
7. For any new construction in the school compound, should be intimated and a permit should be obtained from LSGI. Safety measures such as barricades must be ensured.
8. The electrical wiring in the school building shall be examined by an approved /licenced wireman within one month

Place: Alakode

Date: 29/05/2026




Assistant Engineer
L.S.G.D. Section
Alakode Grama Panchayat
P. O. Alakode-670 571